

25X1

REPORT

## CD NO.

19, February

NO. OF PAGES 1

NO. OF ENCLS. 25X1

SUPPLEMENT TO  
REPORT NO.

THIS IS UNEVALUATED INFORMATION

25X1

Description of the speedboat: Apparently of Soviet type, radar mast mounted on top of bridge house, short and bulky hull, high-sided, one torpedo tube on either side, approximately in the middle of the ship; ~~two~~ canvas covered guns on quarter deck; and only a small anchor capstan and a small rail on the forecastle.  
(See sketch).

25X1

25X1

32

CLASSIFICATION

25X1

25X1

**SECRET**  
**U.S. OFFICIALS ONLY**  
**CLASSIFICATION**

COUNTRY East Germany

REPORT

25X1

SUBJECT Vessels of the NVA/See in the Baltic

DATE OF REPORT 9 April 1958

25X1

DATE OF INFO

LAST REPORT ON SUBJECT  
 (If applicable)

EVALUATION

ANNEXES 1 sketch

APPRAISAL C

25X1

a train of barges of the NVA/See consisting of a navy tender and a speed boat was observed on position 54°25' N / 12°08' E at course 2400. The designation of the tender could not be identified.


Description of the speedboat: Apparently of Soviet type, radar mast mounted on top of bridge house, short and bulky hull, high-sided, one torpedo tube on either side, approximately in the middle of the ship; Two canvas covered guns on quarter deck; and only a small anchor capstan and a small rail on the forecastle.  
 (See sketch).

25X1


Comment. The "tender" is believed to be a lighter for dry cargo of NVA/See.  
 The tugged speedboat presumably is one of the nine vessels of type P-6 turned over to the NVA by the Soviets.  
 The observation in this area is considered normal, (about 6 seamiles south-west of Gedser Rev).  
 For sketches, see Annex.

SECRET - U.S. OFFICIALS ONLY

25X1



25X1



SECRET

25X1